

SAFETY DATA SHEET

Current Revision: 2, 10/29/2015

Prepared By: Ben Ward, Product Engineer

Salem Fabrication Supplies

Winston-Salem, NC 27103

Information: (800) 234-1982

5901 Gun Club Road

I. IDENTIFICATION

EMERGENCY PHONE:

CHEMTREC- (800) 424-9300 CCN:

19481

PRODUCT NAME: Sahara Dry Synthetic Powder Coolant

SYNONYMS: N/A

Recommended Use:

Industrial glass coolant powder Restrictions:


None known

II. HAZARD IDENTIFICATION

Classification (§1910.1200):

Not classified as a hazardous substance under OSHA/GHS.

Signal Word/Symbols:



N/A

Hazard Statement:

N/A

Precautionary Statement:

GO BEYOND THE EDGE

NORTH CAROLINA – HQ

CALIFORNIA

 5901 Gun Club Road
 10125 Shoemaker Avenue

 Winston-Salem, NC 27103
 Santa Fe Springs, CA 90670

 Office:
 800.234.1982 | 336.766.1104
 Office: 800.445.6339 | 562.944.6155

PENNSYLVANIA

2330 Greensburg Road New Kensington, PA 15068 Office: 724.212.3749

WASHINGTON

3801 NE 109th Ave. Suite C Vancouver, WA 98682 **Office:** 360.993.5644

ONTARIO - CANADA

Greater Toronto Area Office: 844.858.7444 www.SalemFTG.com



N/A

Miscellaneous Hazards:

N/A

Unknown Acute Toxicity Statement:

N/A

III. COMPOSITION				
CHEMICAL NAME:	COMMON NAMES:	CAS:	% BY WEIGHT:	
Monopotassium phosphate	Phosphoric acid, monopotassium salt	7778-77-0	>90	

Classified Impurities and Additives:

N/A

IV. FIRST AID MEASURES

Inhalation:

Remove affected person from source of exposure. Get medical attention if breathing difficulty or discomfort persists.

Skin Contact:

First aid not normally required. Remove contaminated clothing. Wash area of contact with soap and water. Wash clothing before reuse. Get medical attention if irritation occurs and persists. **Eye Contact:**

Remove contact lenses. Flush with water until all traces of material are gone. Eyelids should be held away from the eyeball to ensure thorough rinsing. Get medical attention if irritation persists.

Ingestion:

GO BEYOND THE EDGE

NORTH CAROLINA – HQ

5901 Gun Club Road Winston-Salem, NC 27103 Office: 800.234.1982 | 336.766.1104 **CALIFORNIA** 10125 Shoemaker Avenue Santa Fe Springs, CA 90670 **Office:** 800.445.6339 | 562.944.6155

PENNSYLVANIA

2330 Greensburg Road New Kensington, PA 15068 **Office:** 724.212.3749

WASHINGTON

3801 NE 109th Ave. Suite C Vancouver, WA 98682 **Office:** 360,993.5644

ONTARIO - CANADA Greater Toronto Area Office: 844.858.7444 www.SalemFTG.com



Do not induce vomiting because of danger of aspiration into lungs. If conscious, give a glass of water. Never give anything by mouth to an unconscious person. If spontaneous vomiting occurs, monitor for breathing difficulty. Get medical attention.

Symptoms/Effects:

None known.

Level Of Medical Attention Needed:

None known.

V. FIRE-FIGHTING MEASURES

Suitable Extinguishing Media:

All suitable extinguishing media can be used.

Unsuitable Extinguishing Media:

None known.

Specific Hazards:

None known.

Special Protective Equipment:

As with any fire, exposed firefighters should wear MSHA/NIOSH approved self-contained breathing apparatus with full-face mask and full protective equipment.

VI. ACCIDENTAL RELEASE MEASURES

Personal Precautions:

Avoid breathing dust, vapors, mist or gas.

Protective Equipment:

Wear gloves when handling and avoid contact if possible. If dust is present wear a suitable face mask.

Emergency Procedures:

N/A

GO BEYOND THE EDGE

NORTH CAROLINA - HQ

CALIFORNIA

5901 Gun Club Road Winston-Salem, NC 27103 Office: 800.234.1982 | 336.766.1104 Office: 800.445.6339 | 562.944.6155

PENNSYLVANIA

2330 Greensburg Road Office: 724.212.3749

WASHINGTON

Office: 360.993.5644

ONTARIO - CANADA Office: 844.858.7444 www.SalemFTG.com



Methods for Cleanup/Removal:

Sweep of vacuum to collect as dry product. Use absorbents to collect liquids. Keep in suitable, closed containers for disposal. Flush area with water provided runoff does not enter drain or sewer; use absorbent material and dispose of properly.

VII. HANDLING AND STORAGE

Handling Precautions:

Reduce contact when possible and wear gloves. When dust is present wear a face mask and safety glasses.

Safe Storage Conditions:

Product should be stored in a dry location at ambient temperatures below 100. Avoid contact with oxidizers. Reduce dust buildup when possible.

Incompatibilities:

Keep away from strong oxidizers.

VIII. EXPOSURE CONTROLS AND PROTECTIVE EQUIPMENT

OSHA PEL:	ACGIH TLV:	OTHER EXPOSURE LIMITS:
15mg/m ³ avg. for 8hr shift	Click here to enter text.	California OSHA PEL: 10mg/m³ TWA

Appropriate Engineering Controls:

Exhaust ventilation necessary in locations of excessive dust.

Personal Protective Measures:

Face mask and glasses in instances of dust creation. Wear gloves when contact is necessary.

GO BEYOND THE EDGE

NORTH CAROLINA - HQ

5901 Gun Club Road Winston-Salem, NC 27103 **Office:** 800.234.1982 | 336.766.1104 CALIFORNIA 10125 Shoemaker Avenue Santa Fe Springs, CA 90670 Office: 800.445.6339 | 562.944.6155 PENNSYLVANIA

2330 Greensburg Road New Kensington, PA 15068 Office: 724.212.3749 WASHINGTON

3801 NE 109th Ave. Suite C Vancouver, WA 98682 Office: 360.993.5644 ONTARIO - CANADA Greater Toronto Area Office: 844.858.7444 www.SalemFTG.com



IX. PHYSICAL AND CHEMICAL PROPERTIES

Appearance:

Blue powder

Odor: None	Odor Threshold: None	Ph: 6
Melting/Freezing Point: N/A	Boiling Point: N/A	Boiling Range: N/A
Flash Point:	Evaporation Rate:	Flammability (Solid, Gas):
N/A	N/A	N/A
Upper/Lower Flammability/Explosive Limit: N/A	Vapor Pressure: N/A	Vapor Density: N/A
Relative Density: >1	Solubility (ies): Water, good	Partition Coefficient: NOctanol/Water: N/A
Auto Ignition Temperature: N/A	Decomposition Temperature:	Viscosity: N/A
	>338 °F (170 °C)	

X. STABILITY AND REACTIVITY

Reactivity:

None under normal conditions.

GO BEYOND THE EDGE

NORTH CAROLINA - HQ 5901 Gun Club Road

Office: 800.234.1982 | 336.766.1104

CALIFORNIA

10125 Shoemaker Avenue Santa Fe Springs, CA 90670 **Office:** 800.445.6339 | 562.944.6155

PENNSYLVANIA

2330 Greensburg Road New Kensington, PA 15068 **Office:** 724.212.3749

WASHINGTON

3801 NE 109th Ave. Suite C Vancouver, WA 98682 **Office:** 360.993.5644

ONTARIO – CANADA

Greater Toronto Area Office: 844.858.7444 www.SalemFTG.com



Chemical Stability:

Stable under normal conditions.

Possibility of Hazardous Reactions:

None known.

Conditions to Avoid: Static Discharge, Shock, Vibrations, Etc.

None known.

Incompatible Materials:

Strong oxidizers.

Hazardous Decomposition Products:

May produce byproducts of carbon dioxide and carbon monoxide.

XI. TOXICOLOGICAL INFORMATION

Possible Exposure Routes (Inhalation Etc.):

May be abrasive and cause irritation when exposed to eyes, lungs, and skin.

Symptoms Related To Toxicological Characteristics:

None expected.

Delayed, Immediate, and Chronic Effects:

N/A

Numerical Toxicity Measurements:

N/A

NTP/LARC/OSHA Known Carcinogen:

Not a known carcinogen.

ECOLOGICAL INFORMATION XII.

Ecotoxicity:

N/A

GO BEYOND THE EDGE

NORTH CAROLINA - HQ

CALIFORNIA

5901 Gun Club Road Winston-Salem, NC 27103 Office: 800.234.1982 | 336.766.1104

Office: 800.445.6339 | 562.944.6155

PENNSYLVANIA

2330 Greensburg Road New Kensington, PA 15068 Office: 724.212.3749

WASHINGTON

Vancouver, WA 98682 Office: 360.993.5644

ONTARIO - CANADA

Office: 844.858.7444 www.SalemFTG.com



Persistence and Degradability:

Soluble in water. Persistence unlikely.

Bioaccumulative Potential:

N/A

Soil Mobility:

Mobile when mixed with water.

Other Adverse Effects:

N/A

XIII. DISPOSAL CONSIDERATIONS

Waste Residue and Disposal:

Dispose of waste material according to local, state and federal environmental regulations. Components mixed in during use may be hazardous and should be disposed of accordingly.

XIV. TRANSPORT INFORMATION				
UN Number: N/A	UN Proper Shipping Name: N/A	Transport Hazard Class (es): N/A		
Packing Group: N/A	Environmental Hazards: N/A	Transport in Bulk (Annex LI MARPOL 73/78 and IBC Code) N/A		

Special Precautions:

N/A

XV. **REGULATORY INFORMATION**

Environmental/ Health/ Safety:

GO BEYOND THE EDGE

NORTH CAROLINA - HQ 5901 Gun Club Road

Winston-Salem, NC 27103

CALIFORNIA

Santa Fe Springs, CA 90670 Office: 800.234.1982 | 336.766.1104 Office: 800.445.6339 | 562.944.6155

PENNSYLVANIA

2330 Greensburg Road New Kensington, PA 15068 Office: 724.212.3749

WASHINGTON

Vancouver, WA 98682 Office: 360.993.5644

ONTARIO - CANADA

Office: 844.858.7444 www.SalemFTG.com



N/A

XVI. OTHER INFORMATION

This information is furnished without warranty, express or implied, except that it is accurate to the best knowledge of Salem Fabrication Supplies. It relates only to the specific material designated herein, and does not relate to use in combination with any other material or in any process. Salem Fabrication Supplies assumes no legal responsibility for use of or reliance upon this information.

GO BEYOND THE EDGE

NORTH CAROLINA - HQ

5901 Gun Club Road Winston-Salem, NC 27103 **Office:** 800.234.1982|336.766.1104

CALIFORNIA

10125 Shoemaker Avenue Santa Fe Springs, CA 90670 **Office:** 800.445.6339 | 562.944.6155

PENNSYLVANIA

2330 Greensburg Road New Kensington, PA 15068 Office: 724.212.3749

WASHINGTON

3801 NE 109th Ave. Suite C Vancouver, WA 98682 **Office:** 360,993.5644

ONTARIO – CANADA

Greater Toronto Area Office: 844.858.7444 www.SalemFTG.com